



TECH TIPS

Dixie Part Numbers: S-2058

Applications: 1991 – 1996 Ford Aerostar 4.0L
1991 – 1996 Ford Explorer 4.0L with Automatic Transmission
1991 – 1996 Ford Ranger 4.0L with Automatic Transmission

Condition: The operator of the vehicle may complain of unusual noise during cranking. They may also complain of noise/vibration and not being able to shift the transmission into forward and/or reverse.

Cause: A possible cause for the above is a crack in the flexplate.

Correction: Verify that one of the conditions defined above exists. If there is noise during starting verify that the starter functions correctly. If the condition still exists and the starter functions properly then inspect the flexplate. The manufacturer had an earlier flexplate that was prone to cracking. The suspect flexplate is identifiable by 3 large welding spots on the face of the plate evenly spaced around the opening. The revised flexplate is part number F1TZ-6375-BA