



TECH TIPS

Dixie Part Numbers: S-6270, S-6272

Applications: 2008 Volkswagen Beetle (VIN 1C_8M000033 to VIN 1C8M507124 and 1Y_8M000029 to 1Y_8M406643)

Condition: The operator of the vehicle may comment that the battery is discharged after 5 days in storage.

Cause: A possible cause for this is excessive parasitic/quiescent draw. A trunk warning light input to the instrument cluster is a possible cause for the excessive draw.

Correction: With the vehicle locked using the remote key wait approximately 15 minutes for all systems to go into the sleep mode. Measure the system current draw. If the draw is more than 325mA further diagnostics is required. Follow the manufacturer's recommended procedures to determine the cause and if required install a diode in the wiring harness at the instrument panel (dealer part number 1Y0 970 082).