



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009 – 2010 Cadillac CTS-V
2009 – 2010 Chevrolet Corvette ZR1

Condition: The operator of the vehicle may complain that the belt squeals or squeaks.

Cause: A potential cause for the above condition is a misaligned belt.

Correction: Follow the manufacturer's recommended inspection procedures to ensure the belts are properly aligned. If required, replace the belts with the appropriate ones. The manufacturer lists 12636227 for the Cadillac CTS-V and 12637321 for the Chevrolet Corvette.