



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2011 Chevrolet Express G Series Van 6.6L Diesel
2010 – 2011 Chevrolet Silverado 6.6L Diesel
2010 – 2011 GMC Savana 6.6L Diesel
2010 – 2011 GMC Sierra 6.6L Diesel

Condition: The operator of the vehicle may complain of a failure to start, a hard start or an extended crank cycle. After the engine starts it functions properly.

Cause: A potential cause for the above condition is the Filter Minder Vacuum Switch.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures.