



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Buick Enclave 3.6L
2010 Chevrolet Traverse 3.6L
2010 GMC Acadia 3.6L
2010 Saturn Outlook 3.6L

Conditions: The operator may complain of extended starter cranking time when the ambient temperature is 10-15°C /50-60°F.

Cause: A potential cause for the above condition is a flaw in the initial engine control module calibration file.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures and update the engine control module calibration file only when required.