



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2012 Chevrolet Express with Gasoline Engine
2010 – 2012 GMC Savana with Gasoline Engine

Conditions: The operator of the vehicle may complain of a chirp sound while starting the engine in colder temperatures. The technician may trace the sound to the power steering pump.

Cause: A potential cause for the above condition is the viscosity of the power steering fluid.

Correction: Follow the manufacturers recommended power steering fluid replacement procedures which include flushing out the factory installed fluid and replacing it with the appropriate replacement fluid, available through the dealership network:

Canada (and cold climates)	10953471
US (and warmer climates)	12345867