



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2011 MCI D4505

Conditions: The operator of the vehicle may complain of erratic electrical problems including low/dead batteries, hard starting conditions or an engine compartment fire.

Cause: A potential cause for the above condition is water contamination on the alternator battery terminal, causing the terminal to corrode and develop a high voltage drop.

Correction: Follow the manufacturer's inspection and repair procedures when applicable.