



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Audi A3
2010 Audi TT

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- A low or dead battery.
- Intermittent slow or hard cranking.
- The alarm sounds for no reason.

Cause: A potential cause for the above condition is a software flaw with the timing of the alarm system.

Correction: The manufacturer has released a software update to correct the problem. Follow the manufacturer's recommended procedures to diagnose and update the software when applicable.