



TECH TIPS

Dixie Part Numbers: S-6212 and S-6213

Applications: 1999 – 2000 Saab 9-5

Condition: Some vehicle owners may complain of excessive cranking times, more predominantly when the fuel tank is less than $\frac{1}{4}$ full.

Cause: A potential cause for this is the fuel pump.

Correction: The vehicle manufacturer recommends replacing the fuel pump with OE part number 41 60 511. Service kit 53 34 198 will also be required. Follow the manufacture's recommended procedures for changing the fuel pump.