



TECH TIPS

Dixie Part Numbers: S-6229 S-6258

Applications: 2004 BMW X5

Condition: The operator of the vehicle may complain of the engine stalling after a short period of operation and failing to restart.

Cause: A potential cause for the above is a faulty Powertrain Control Module (or ECM).

Correction: Follow the manufacturer's recommended procedures for inspecting, testing and replacing the Powertrain Control Module (if required). Please note that the NHTSA issued a campaign, ID number 04V344000 to address this issue.