



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Can-Am Roadster Spyder RS SE5
2010 Can-Am Roadster Spyder RT SE5

Condition: The operator of the vehicle may complain that the engine has stalled when coming to a stop and can not be restarted additionally the semiautomatic transmission remains in gear and blocks the rear wheel.

Cause: A possible cause for the above condition is a flaw in the semiautomatic transmission.

Correction: The manufacturer has issued a recall on this issue and will fix it at no charge to the owner of the vehicles.