



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Volkswagen Routan 4.0L

Condition: The operator of the vehicle may complain of a hard starting condition in cold ambient temperatures. The malfunction indicator lamp may come on and the technician may find code P050D stored in the power train control module.

Cause: A potential cause for the above is an error in the software for the power train control module.

Correction: Follow the manufacturer's recommended procedures for updating the power train control module software, if required.