



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 BMW 5 Series (all models)

Condition: The operator of the vehicle may complain that one of the following warnings is displayed:

- Power Supply
- Check
- Battery heavily discharged

The technician may find diagnostic trouble code 213B08 retained in the vehicle's systems.

Cause: A potential cause for the above condition is the vehicle Digital Engine Electronics software (DME in BMW terminology).

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable. The updated software is revision dated September 2010 or later (ISTA/P 2.39).