



TECH TIPS

Dixie Part Numbers: S-6166

Applications: 1981 – 1982 Alfa Romeo GTV-6

Condition: The operator of the vehicle may complain that the starter does not crank on an intermittent basis.

Cause: A potential cause for the above condition is a faulty ignition switch assembly.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures and replace the ignition switch if required.