



TECH TIPS

Dixie Part Numbers: S-6155 S-6258 TBA

Applications: 2008 BMW 730 d and dL
 2008 BMW 740 i and iL
 2008 BMW 750 i and iL

Condition: The operator of the vehicle may complain that the vehicle fails to start and the ignition cannot be switched on. The vehicle can be opened using the remote and a message is displayed indicating that the engine can only be started via the emergency coil on the steering column.

Cause: A potential cause for this a flaw in the receiver antenna in the module.

Correction: Follow the manufacturer’s recommended repair procedures when applicable.