



TECH TIPS

Dixie Part Numbers: A-80409

Applications: 1990 – 2000 Honda GL1500
Gold Wing

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- There is vibration at idle
- There is a “clunk” sound on deceleration

Cause: The coupling cushion for the alternator may be worn out or the rubber deteriorated.

Correction: It is recommended that when replacing the alternator that the coupling cushion be replaced as well. Verify with your distributor as some sell these individually versus as a kit of 4 (required).

