



TECH TIPS

Dixie Part Numbers: S-8686 S-80019

Applications: 2005 Acura TL

Condition: The above vehicles were subject to a recall for a failure to start.

Cause: The cause was identified as a fault in the fuse box that would cause the fuel pump fuse to become loose resulting in the engine shutting down and failing to restart.

Correction: The manufacturer recommends replacing the entire fuse box. The dealership network is to perform this task free of charge.