



TECH TIPS

Dixie Part Numbers: S-80017

Applications: 2005 Acura TSX

Condition: The above vehicles were subject to a recall for a failure to start.

Cause: The recall notice identifies the source of the problem as a loose coil wire inside the fuel pump relay that was prone to breaking resulting in the engine shutting down and not restarting.

Correction: The manufacturer recommends replacing the fuel pump relay. The dealership network is to perform this task free of charge.