



TECH TIPS

Dixie Part Numbers: A-1639 A-8955 A-80032 A-80291

Applications: 2003 – 2007 Honda Accord V6
 2005 – 2006 Honda Odyssey
 2005 – 2006 Honda Pilot 4WD
 2006 – 2007 Honda Ridge Line

Condition: The technician may encounter interference issues when replacing the alternator auto-tensioner.

Cause: The rib on the lower timing belt cover interferes with auto-tensioner.

Correction: Follow the manufacturer's recommended procedures to modify the rib on the lower timing belt cover to allow for proper clearance.