



TECH TIPS

Dixie Part Numbers: S-80321 S-80322 S-80323 S-80410

Applications: 2008 Honda Accord (all 2 and 4 door models)
2009 Honda Accord
- 2 door VIN 1HGCS1...9A000001 to 1HGCS1...9A004953
- 4 door VIN 1HMCP2...9C000001 to 1HMCP2...9C010096

Condition: The operator of the vehicle may complain that when starting the engine cold that there is a loud rattle for about 2 seconds after the engine starts.

Cause: A potential cause for the above condition is a defective variable timing control actuator.

Correction: Follow the manufacturer's recommended procedures to repair the variable timing control actuator.

