



TECH TIPS

Dixie Part Numbers: S-80464

Applications: 2009 Pontiac Vibe 1.8L FWD

Condition: The operator of the vehicle may complain of one or more of the following conditions:

- The engine is hard to start after a cold soak.
- The malfunction indicator light is illuminated.

The technician may find diagnostic codes P0015, P0300, P0301, P0302, P0303 and/or P0304 stored in the system.

Cause: A potential cause for the above conditions is a carbon build up in the cylinders.

Correction: The manufacturer has released a calibration file update to address the above problem. Follow the manufacturer's recommended diagnostic and repair procedures.