



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2011 Nissan Sentra

Condition: The operator of the vehicle may complain that the engine stalls at low speed, is difficult to start or fails to crank and start.

Cause: The positive battery bolt and washer assembly may have been manufactured incorrectly, leaving a gap between the cable and contact area of the battery. This may result in a significant voltage drop and may cause the engine to stall, prevent the engine from starting or damage the vehicle's onboard electronics.

Correction: Follow the manufacturer's recommended procedures to inspect and replace the positive battery cable end, as required.

