



TECH TIPS

Dixie Part Numbers: S-80280

Applications: 2008 Cadillac SRX

Conditions: The operator of the vehicle may comment on an intermittent no start condition. The technician, when replacing the starter battery cable, may notice that the replacement battery cable is shorter then the cable being removed.

Cause: A potential cause for the above condition is the routing for the starter battery cable has been changed to prevent chaffing.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable.