



TECH TIPS

Dixie Part Numbers: A-80007, A-80008

Applications: 2001 – 2003 Chrysler Town & Country (3.3L and 3.8L)
2001 – 2003 Dodge Caravan (3.3L and 3.8L)

Condition:

The operator may complain of the battery light being illuminated. Diagnostic scan code P1594 – “charging system voltage too high” is stored in the memory.

Cause:

A potential cause for the above to occur is an error in the programming in the vehicle control module.

Correction:

Perform the manufactures’ recommended diagnostic and memory flashing procedure.