



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Honda Accord 2 door (VIN 1HGCS1..AA003602 to VIN 1HGCS1..AA004331)
2010 Honda Accord 4 door (VIN 1HGCP2..AA037687 to VIN 1HGCP2..AA043947)
2010 Honda CR-V 2WD (VIN 5J6RE3..AL005827 to VIN 5J6RE3..AL006366)
2010 Honda CR-V 4WD (VIN 5J6RE4..AL011857 to VIN 5J6RE3..AL011916)

Conditions: The operator of the vehicle may complain of the engine stalling and failing to restart or cranking without starting.

Cause: A possible cause for the above conditions a loose wire connection in the C101 engine wiring harness.

Correction: Follow the manufactures recommended diagnostic and repair procedures which include inspecting the VIN in the engine compartment, vehicles already inspected and repaired by the dealership network will have a punch mark above the first digit.