



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2008 – 2010 Kawasaki Ninja ZX-10R
2009 – 2012 Kawasaki Ninja ZX-6R



Cowasaki Ninja

Conditions: The operator of the vehicle may complain of one or more of the following conditions:

- A failure to crank or start.
- The engine stalls and cannot be restarted.

When testing the electrical system the technician may observe lower than the normal voltage of 14V.

Cause: A potential cause for the above conditions is a manufacturing flaw in the voltage regulator/rectifier assembly resulting in the voltage setting to be too low.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures when applicable.