



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2011 – 2012 Lexus RX350

Conditions: The operator of the vehicle may complain that the charge malfunction indicator malfunction indicator light comes on, that the battery is low or dead.

Cause: A potential cause for the above conditions is the clutch pulley on the alternator.

Correction: The pulley may be eligible for replacement under the manufacturer's warranty, depending on the age and mileage of the vehicle. Follow the manufacturer's diagnostic and repair procedures when applicable.