



TECH TIPS

Dixie Part Numbers: S-8713 and S-8714

Applications:

2002 Chrysler Concorde, Intrepid, 300M or LH models built prior to January 28, 2002 (MDH 0128XX).

Condition:

The vehicle may demonstrate one or more of the following problems:

- Fails to start, cranks with out starting or the engine misfires with diagnostic codes P0351, P0352, P0353, P0354, P0355m P0356 ignition coil primary circuit failure.
- The transaxle is in limp-in mode with diagnostic codes P0750, P0755, P0760, P0765 or solenoid continuity errors.

Cause:

A possible cause is the PCM programming, a clogged catalytic converter, faulty ignition coil, faulty ignition wires or faulty spark plugs.

Correction:

Follow the manufacturer's recommended procedures for trouble shooting the system.