



TECH TIPS

Dixie Part Numbers: A-80349

Applications: 2007 Toyota Yaris

Condition: The charge system warning light may indicate charge system errors.

Cause: A potential cause for this is corrosion in the alternator on the voltage regulator terminals.

Correction: The manufacturer recommends changing the voltage regulator or the alternator.

Revision 20090819 Corrected part number

REV: 20090819

Courtesy of APRA

TSB_819.doc

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.