



TECH TIPS

Dixie Part Numbers:

A-6530	A-80286	A-80307	A-80353	S-80393
A-80036	A-80287	A-80308	A-80354	S-8455
A-80037	A-80288	A-80310	A-8910	S-8738
A-80072	A-80289	A-80311	A-8914	S-8772
A-80276	A-80290	A-80328	A-8971	S-8976
A-80284	A-80300	A-80329	S-80007	
A-80285	A-80306	A-80336	S-80384	

Applications: 2006 Lexus all models
2006 Scion TC
2006 Toyota All models

Condition: When servicing any of the above vehicles and the power is disconnected, accessories such as (when applicable) but not limited to may not function correctly when power is restored:

- Rear door power window
- Compass
- Power windows
- Power back door
- Power sliding door
- Sliding roof

Each device may require initialisation or they may not function correctly.
The same condition may occur if the voltage drops below 7 volts.

Cause: The settings for each device are stored in microcomputers, which lose their settings when power is disconnected.

Correction: When disconnecting the power for any reason, follow the manufacturer's recommended procedures for initialising each electrical device in the system. For Hybrid vehicles also refer to TSB-839.

Rev 20090819: Corrected part number A-6530 was entered as A-6350, added S-80007

Rev 20100308: Removed A-80305, superseded to A-80036. Added A-80036