



TECH TIPS

Dixie Part Numbers: S-8032 S-8192

Applications: 1985 – 1988 Toyota 4Runner (22R-E, 22R-TE)
1985 – 1988 Toyota Pickup (22R-E, 22R-TE)

Condition: The operator of the vehicle may complain of hard starting, extended cranking times or a rough idle speed.

Cause: Two possible causes for the above are an improperly calibrated temperature switch (switch number 2) or an improperly calibrated cold start injector switch.

Correction: Follow the manufacturer's recommended procedures for verifying the above condition, replacing the recommended parts and modifying the vehicle's wiring harness when instructed.