



TECH TIPS

Dixie Part Numbers: S-8686 S-80016 S-80017 S-80312

Applications: 2005 Acura TL
2005 Honda Accord
2005 Honda Odyssey

Condition: The operator of the vehicle may complain that the vehicle cranks but fails to start. This may or may not have occurred following the engine stalling while operating under normal conditions.

Cause: A possible cause for the above condition is a loose terminal inside the main fuse box that may cause the fuel pump to become inoperative.

Correction: Follow the manufacturer's recommended diagnostic and repair procedure (if required). Please note that this condition was part of a NHTSA Campaign ID number 05V132000)