



TECH TIPS

Dixie Part Numbers: A-9376, A-9377, S-1466 and S-6236

Applications: 2002 – 2003 Saturn Vue

Condition:

The operator or the vehicle may complain of one or more of the following conditions:

- The starter remains engaged after the engine has started.
- Accessories such as the radio, power windows or heating/air-conditioning fan may intermittently loose power.

Cause:

A possible cause for the above conditions may be the ignition lock bolt release spring binding located inside the ignition and start switch housing assembly.

Correction:

To correct this the ignition and start switch housing must be replaced following the manufacturer's recommended procedure.