



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2009-2010 Hyundai Sonata 2.4L with Valeo Mexico Starters

Condition: The operator of the vehicle may complain of an intermittent no start condition when operating the vehicle below freezing conditions.

Cause: The solenoid was not manufactured to operate in sub-zero climates.

Correction: The manufacturer recommends replacing the solenoid or starter with one that will operate in colder climates.