TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 Buick LaCrosse[1]
2010 Cadillac SRX[1]
2010 Chevrolet Equinox[1]
2010 GMC Terrain[1]

1) Equipped with a 3.0L or 3.6L V6 engine and built prior to February 27, 2010

Condition: The operator of the vehicle may complain of intermittent belt noise.

Cause: A potential cause for the above condition is one of the following:
- The power steering pump may be misaligned.
- The accessory drive pulley may be misaligned or bent.
- The drive belt may be worn and require replacing.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures if applicable.

Dixie *Tech Tips* are intended for use by professional technicians, and are not for the general public. They are written to inform technicians of conditions that may exist or as a guide to aid in diagnosing and servicing a vehicle. All references to original equipment manufactures, vehicle manufactures and any other Trade Mark names are for the sole purpose of identifying the vehicle and or part that the *Tech Tip* applies to. This document is property of Dixie Electric Ltd. and is not to be copied or distributed with out written permission.