File in the

prestolite

PARTS and EQUIPMENT BINDER

ASSY. NO. ETQ-4001

SALES NO. P40-287

PUMP MOTOR PARTS LIST

ISSUED 7-8-68

Application Minnesota Automotive

Service Part No.	No. Used	Part Description	Prestolite Sales No.
EML-2206	1	ARMATURE ASSY.	P41-96
ETQ-1005	1	COIL ASSY.,FIELD,COMPLETE	P40-288
	2	Screw,Pole Shoe	
	1	Insulation,Field Connection	
	2	Grommet	
EML-2202	1	HEAD ASSY.,COMM.END	P40-289
EWF-12S	1	BRUSH SET	P42-17
	2	Lockwasher,Thru Bolt,#10	
	2	Nut,Thru Bolt,Hex.#10-32	
EWM-18S	1	SPRING SET,BRUSH	P50-136
EWM-23S	1	THRU BOLT PKG.	P43-368
P90-455	1	THRUST WASHER & SPACER PKG.	P90-455
	1	Spacer,D.E. & C.E.	
	2	Washer,Arm.Thrust,1/64"Thick	
	2	Washer,Arm.Thrust,1/32"Thick	
	2	Washer,Arm.Thrust,.023"Thick	

Note:BOLD TYPE ITEMS indicate recommended Prestolite service parts.

PRINTED IN U.S.A.

prestolite®

SERVICE PARTS LIST

ASSY. NO. ETQ-4002

SALES NO. 40-298

PUMP MOTOR

ISSUED 7-6-72

Application Minnesota Automotive

Service Part No.	No. Used	Part Description	Prestolite Sales No.
EML-2606	1	ARMATURE ASSY.	41-118
ETQ-1005	1	COIL ASSY.,FIELD,COMPLETE	40-288
	2	Screw,Pole Shoe	
EML-2202	1	HEAD ASSY.,COMM.END	40-289
ESQ-12S	1	BRUSH SET	42-32
EWM-18S	1	SPRING SET,BRUSH	50-136
EWM-23S	1	THRU BOLT PKG.	42-368
90-455	1	THRUST WASHER & SPACER PKG.	90-455
	1	Spacer,D.E. & C.E.	
	2	Washer,Arm.Thrust,1/64"Thick	
	2	Washer,Arm.Thrust,1/32"Thick	
	2	Washer,Arm.Thrust,.023"Thick	

Printed in U S A

File in the
OE-92 PARTS BINDER

SMALL MOTOR SECTION