



TECH TIPS

Dixie Part Numbers:	A-6407	A-6516	A-6541	A-6556
	A-6557	A-6571	A-9361	A-9505
	A-9507	S-6246	S-6273	

Applications: 2006 – 2007 BMW 3 Series (E90 models)

Condition: The battery-disconnect switch, if removed and installed with the “thin” nut may cause the battery terminal to overheat.

Cause: The “thin” nut that originally held the battery disconnect switch in place does not have a large enough surface area to carry the current to the battery.

Correction: Use a taller nut with a wide flange on the base to ensure that there is a good electrical connection to the terminals.