



TECH TIPS

Dixie Part Numbers: A-80222 S-80308

Applications: 2008 Infiniti G37

Condition: The operator of the vehicle may complain of low voltage, dead batteries or a no crank, no start condition.

Cause: A potential cause for the above conditions is the system electrical demands and the operators driving habits. Operators that drive frequent short trips may have the battery run down as the alternator does not have a chance to replenish the charge.

Correction: Follow the manufacturer's recommended diagnostic and repair procedure which may include, depending on the options installed and serial number, replacing the body control module, the battery, the vent control valve or simply reprogramming the engine control module.