



TECH TIPS

Dixie Part Numbers: S-80464

Applications: 2009 – 2010 Pontiac Vibe
(US models without the Anti-theft package UA6)

Condition: The operator of the vehicle may complain that the starter does not crank on an intermittent basis.

Cause: A potential cause for the above condition is that the system is trying to communicate with the immobilizer... which was not installed, causing the system to go into an error.

Correction: Follow the manufacturer's recommended diagnostic and repair procedures if applicable.