VENSEL ENTERPRISES
3710 Riverside Drive
Crystal Lake, IL
60014
800-662-6099

New Products

Introducing our NEW K108-0700 Drive Rebuilding Fixture

Supplied with 10 tools to remove and install Snap Ring Retainers and Snap Rings. This tool will also remove bearings and aid in rebuilding the clutch pack when used with our option tools



Completely disassemble these Nippondenso drives in far less than 5 minutes and reassemble in the same amount of time.

Nippondenso - (reference numbers)

Accurate	*WAI*	*PIC*
4-676	54-8202	6190-2610
4-788	54-8210	6190-2611
4-1034	54-8224	6190-2616
4-1036	54-8235	6190-2618
4-1045	54-8226	6190-2614
4-1097	54-8218	6190-2620



Change the Gears on these Hitachi drives in less then three minutes.
Remove and Install the Snap Ring Retainer & Snap Ring.
Tooling for Bearing Removal is not suppled.

Hitachi - (reference numbers)
(not supplied for bearing removal)

Accurate	*WAI*	*PIC*
4-751	54-8111	6104-2545
4-678	54-8194	6104-2557
4-798	54-8141	6104-2662
4-896	54-8132	6104-2576
4-899	54-8133	6104-2589
4-905	54-8125	6104-2660
4-910	54-8138	6104-2600
4-911	54-8139	6104-2814



A complete Operation Manual with pictorial aid is available.
Call or email for .PDF copy.

Email: vensel7@comcast.net Web Site: venselenterprises.com