FAIRBANKS MORSE
A MAJOR INDUSTRIAL COMPONENT OF
FAIRBANKS WHITNEY

INSTRUCTIONS SERVICE KIT SK30 TYPE FME6B16 MAGNETOS

MAGNETO and ENGINE ACCESSORIES DIVISION • BELOIT, WISCONSIN

Due to changes in engineering design and material, the end caps Q2430A and X2430A and the distributor block T2474 are no longer available as service items on the Type FM-E6B16 magnetos.

When these items are required, order an SK30 Service Kit. The parts in this kit are interchangeable, as a unit, with the original parts in the magneto. The SK30 Service Kit contains a new end cap cover, end cap, distributor rotor, all necessary gaskets, and screws to convert your magneto into an up-to-date unit.

In the event the items in paragraph one above are ordered, the SK30 Service Kit will be substituted and shipped.