Bulletin FM130

FAIRBANKS-MORSE

MAGNETO SALES INFORMATION

Distributors and-Service Stations
Coil for one Cylinder Type "Z" Engine Magnetos
Notice: Imporant Change

To increase the efficiency and improve the starting performance of the FM-J1 magneto on Fairbanks-Morse Type Z Engines, a new coil has been developed.

The part number for this coil is M2477 and it will be used only on the FM-J1A2, FM-J1B2, FM-J1B2A and FM-J1B2B magnetos.

The L2477 coil which to date has been the standard one cylinder coil will still be used in all FM-J1 applications with the exception of the specifications shown above.

Where a magneto of either of these specifications is returned for service and careful check shows the failure is caused by this breakdown of the coil L2477, the new coil M2477 should be used for replacement.

FAIRBANKS, MORSE & CO.
Magneto Sales
Beloit, Wis.

Bulletin FM130
July, 1947

File Section- *SERVICE INFORMATION*

Printed in U.S.A.