prestolite

SERVICE PARTS LIST

ASSY. NO. ETW-4206

SALES NO. 40-527

HEADLIGHT TILT MOTOR

ISSUED 1/29/87

Application Vista Industries

| Service Part No. | No. Used | Part Description | Prestolite Sales No. |
|---|---|---|---|
| ETW-2106A | 1 | ARMATURE | 41-155 |
| ETW-1105S | 1 | FIELD COIL PACKAGE | 40-528 |
| ETN-1012S | 1 | BRUSH SET | 42-53 |
| | 1 | Insulation, Field Coil | |
| 90-2902 | 1 | GEAR, CAM, & SWITCH PLATE PKG. | 90-2902 |
| XA-744BGS | 1 | O-RING & GASKET PACKAGE | 40-529 |
| | 5 | Screw, Switch Plate Mtg. | |
| ETW-1002S | 1 | HEAD ASSEMBLY, COMM. END | 40-530 |
| ETN-1012S | 1 | BRUSH SET | 42-53 |
| ETW-1003BS | 1 | HEAD ASSEMBLY, DRIVE END | 40-531 |
| * | 1 | Gasket | |
| ETN-33 | 1 | LEAD ASSEMBLY | 26-357 |
| ESR-18AS | 1 | SPRING SET, BRUSH | 50-421 |
| EWJ-20S | 1 | THRU BOLT PACKAGE | 43-416 |
| 90-2903 | 1 | THRUST WASHTER & RETAINER PKG. | 90-2903 |

* Also serviced in XA-744BGS Package.

sys.

Printed in U.S.A.

File in the
OE-92 PARTS BINDER

WIPERS & SMALL
MOTOR SECTION