prestolite®

SERVICE PARTS LIST

ASSY. NO. MAJ-4040

SALES NO. P46-2

STARTING MOTOR PARTS LIST

ISSUED 2-6-69(Rev.)

Application Continental Motors

Service Part No.	No. Used	Part Description	Prestolite Sales No.
MAJ-2046	1	ARMATURE	P16-4
MAB-1024E	1	BAND,COVER	P36-145
MAB-2040	1	BEARING ASSY.,INTERMEDIATE	P36-1
	1	Bearing,Abs.Bronze	
EB-87	1	BENDIX DRIVE(ECLIPSE #A-1583)	P59-59
**	2	Brush	
MAJ-3005S	1	FIELD COIL PACKAGE	P20-96
	4	Screw,Pole Shoe	
MAB-2002	1	HEAD ASSY.,COMM.END	P19-1
**	2	Brush,Grounded	
MZ-19S	1	SPRING SET,BRUSH	P50-263
PS-1043S	1	HOUSING ASSY.,PINION	P21-141
MP-41A	1	BEARING,ABS.BRONZE	P24-28
	1	Pin,Dowel	
	1	Insulation,Field Connection	
	1	Key,Woodruff,D.E.,#6	
	2	Lockwasher,Term.Stud,5/16	
	2	Lockwasher,Thru Bolt,1/4	
	1	Nut,Cover Band,Square #10-32	
	2	Nut,Term.Stud,Hex.5/16-24	
	2	Pin,Dowel	
	1	Screw,Cover Band,Rd.Hd.#10-32x1 1/2	
P90-386	1	TERMINAL STUD PACKAGE	P90-386
	1	Bushing,Ins.,Term.Stud	
	1	Stud,Terminal,5/16-24	
	1	Terminal	
	1	Washer,Ins.,Term.Stud,Inner	
	1	Washer,Ins.,Term.Stud,Outer	
	1	Washer,Plain,Term.Stud,5/16	
MAJ-20S	1	THRU BOLT PACKAGE	P36-582
P90-473	1	THRUST WASHER PKG. *	P90-473
	2	Washer,Thrust,C.E. & Int., 1/32"Thick	
MAB-2012AS	**	BRUSH SET,SERVICE	P17-1

* Contains additional parts to service other applications.

Note:BOLD TYPE ITEMS indicate recommended Prestolite service parts.