prestolite

SERVICE PARTS LIST

ASSY. NO. MSF-4001

SALES NO. [PB]

PUMP MOTOR

ISSUED 9-21-79 Rev.: 6-13-83

Application Clark Equipment #3798295 "Private Brand"

Service Part No.	No. Used	Part Description	Prestolite Sales No.
[PB]	1	ARMATURE & FAN ASSEMBLY	[PB]
MKB-32SS	1	SPLINE & PIN PACKAGE	36-973
PU-707ASC	1	FAN	34-712
[PB]	1	BAND,COVER	[PB]
X-4608SC	1	BEARING,BALL,SEALED,C.E.	25-79
MGP-1012KS	1	BRUSH SET,SERVICE	17-220
MJB-19S	1	CABLE TIE PACKAGE(10PCS.)	36-1058
[PB]	1	FIELD COIL PACKAGE	[PB]
*	1	Insulation,Field Connection	
	1	Insulation,Field Coil	
*	1	Connector & Stud Assembly	
*	1	Stud,Hex.Hd.,3/8-16x1 5/8	
[PB]	1	HEAD ASSEMBLY,COMM.END	[PB]
MGP-18S	1	SPRING SET,SERVICE	50-375
90-2488	1	BRUSH HOLDER KIT	90-2488
[PB]	1	HEAD ASSEMBLY,DRIVE END	[PB]
X-4607SC	1	BEARING,BALL,SEALED	25-78
	1	Retainer(Truarc#N5002-244)	
90-2612	1	POLE SHOE SCREW PACKAGE	90-2612
[PB]	1	SEAL,OIL	[PB]
[PB]	1	TERMINAL STUD PKG.(HDWE.INCL.)	[PB]
X-4236SC	1	WASHER,SPRING,C.E.BEARING	36-847

* Also serviced in Terminal Stud Pkg.

Note:This is a Ventilated Motor; for totally enclosed Motor(2755703) use SP-6119(2755662) Enclosing Kit.

[PB] Private Brand Part - not available thru Prestolite.