prestolite®

SERVICE PARTS LIST

ASSY. NO. MSK-4001

SALES NO. 46-2746

PUMP MOTOR

ISSUED 2/26/80 Rev. 7/6/88

Application Raymond Corp. #570-214/101

Service Part No.	No. Used	Part Description	Prestolite Sales No.
MJC-2186	1	ARMATURE	16-888
X-4612	1	BEARING, BALL, SEALED, C.E.	25-83
MJB-19S	1	CABLE TIE PKG. (10 PCS.)	36-1058
GAL-40CSC	1	COVER, C.E. BEARING	36-105
MSK-3005S	1	FIELD COIL PKG.	20-721
*	1	Insulation, Field Connection	
*	1	Stud, Hex.Hd. 5/16-18x1-3/4"	
MJB-1122AS	1	HEAD ASSEMBLY, COMM. END	19-379
MGP-18SS	1	SPRING SET, BRUSH	50-368
*	1	Insulator, Terminal Stud	
*	1	Connector, Strap	
MGQ-1016A	1	PLATE ASSEMBLY, BRUSH	36-919
*	1	Connector & Stud Assembly	
MGQ-2012BS	1	BRUSH SET, SERVICE	17-235
MGQ-1123A	1	HEAD ASSEMBLY, DRIVE END	22-350
X-5390	1	BEARING, BALL, SEALED	25-104
90-2610	1	POLE SHOE SCREW PACKAGE	90-2610
90-2480	1	TERMINAL STUD PKG.(HDWE. INCL.)	90-2480
X-4079SC	1	WASHER, SPRING, C.E. BEARING	39-451

* Also serviced in Terminal Stud Pkg.

Note: This is a ventilated motor, for totally enclosed motor, use SP-6130 (70-71) enclosing kit.

Printed in U.S.A.

File in the
OE-92 PARTS BINDER

MOTOR

prestolite®

SERVICE PARTS LIST

ASSY. NO. MSK-4002

SALES NO. 46-2556

PUMP MOTOR

ISSUED 6-15-82 Rev.: 6-15-83

Application Allis-Chalmers (Military)

Service Part No.	No. Used	Part Description	Prestolite Sales No.
MJC-2186	1	ARMATURE	16-888
X-4612	1	BEARING,BALL,SEALED,C.E. #203	25-83
MJB-19S	1	CABLE TIE PKG.,COIL CONN.(10PCS.)	36-1058
GAL-40CSC	1	COVER,C.E.BEARING	36-105
MSK-3005S	1	FIELD COIL PACKAGE	20-721
*	1	Insulation,Field Connection	
*	1	Stud,Hex.Hd.,5/16-18x1 3/4"	
MJB-1122AS	1	HEAD ASSEMBLY,COMM.END	19-379
MGP-18SS	1	SPRING SET,BRUSH	50-368
*	1	Connector,Strap	
MGQ-1016A	1	PLATE ASSEMBLY	36-919
MGQ-2012BS	1	BRUSH SET,SERVICE	17-235
*	1	Connector & Stud Assembly	
*	1	Insulator,Terminal Stud	
MGQ-1123A	1	HEAD ASSEMBLY,DRIVE END	22-350
X-5390	1	BEARING,BALL,SEALED,#105	25-104
90-2610	1	POLE SHOE SCREW PKG.	90-2610
90-2480 +	1	TERMINAL STUD PKG.(HDWE.INCL.)	90-2480
X-4079SC	1	WASHER,SPRING,C.E.BEARING	39-451

* Also serviced in 90-2480 Pkg.

+ Contains additional parts to service other applications.

Note:This is a Ventilated Motor; for totally enclosed Motor use SP-6130 (70-71) Enclosing Kit.

Printed in U S A

File in the
OE-92 PARTS BINDER

MOTOR SECTION