




P.T.O. SWITCH	
OFF	B+E, C+D
ON	B+A

KEY SWITCH	
OFF	NONE
RUN	B+I+A
START	B+I+S