




PTO SWITCH	
OFF	B+E, C+D
ON	B+A

KEY SWITCH	
OFF	NONE
RUN w/LIGHTS	B+I+R+L
RUN	B+I+R
START	B+I+S