



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2011 Chevrolet Express (G Series Van) 4.3L, 4.8L or 6.0L Gasoline Engine
2010 – 2011 GMC Savana (G Series Van) 4.3L, 4.8L or 6.0L Gasoline Engine

Conditions: The operator of the vehicle may complain that intermittently the engine will crank but fails to start.

Cause: A possible cause for the above condition is a poor connection on the under hood bussed electrical center (UBEC) X2 connection. This connection supplies power to the fuel pump and has been observed to be an issue in the field.

Correction: Follow the manufactures recommended diagnostic and repair procedures which may include replacing the UBEC connector or the individual terminals, when applicable.