



TECH TIPS

Dixie Part Numbers: TBA

Applications: 2010 – 2012 Buick LaCrosse
2010 – 2012 Cadillac SRX
2010 – 2012 Chevrolet Camaro
2010 – 2012 Chevrolet Equinox
2010 – 2012 GMC Terrain
2011 – 2012 Buick Regal
2011 – 2012 Chevrolet Cruze
2011 – 2012 Chevrolet Volt
2012 Buick Verano
2012 Chevrolet Sonic
2013 Chevrolet Malibu

Conditions: The technician may find various diagnostic codes stored in the system history after performing work on the electrical system of the vehicle, particularly if the engine control module is woken up with any of the 5V reference sensors unplugged.

Cause: The codes are stored in history until the GDS2 scan tool is used to reset them, even if they have been rectified and resolved.

Correction: Follow the manufacturer's recommended procedures for diagnosing problems and clearing diagnostic trouble codes. When using the GDS2 software Always follow the circuit system verification prior to proceeding with circuit system testing.